

Problem/Failure Report THM_PFR_107

PFR-107 Title: FM 3 SEA Dropped			
Assembly: SST		SubAssembly : SEA	
Component : S/N 16-21		Units Affected:	Units fixed:
Originator: Christopher Scholz		x	x
Organization: SSL		Date: October 13, 2005	
Phone: 510-643-2478		Email: cscholz@ssl.berkeley.edu	
□ Functional test □	d During (Check one √) Qualification test □ S/C Integr nen failure occurred: □ Vibration □ Vacuum	ation □ Launch operation □ Shock □ Thermal-Vacuum	S X Other (Flight Assy) □ Acoustic □ EMI/EMC
		Description	
enclosed in their ESI reaching for the door and dropped to the fl The SEA w. frame or the electron The SEA w.	A's were being transported from D Anti-Stat bags, which were play of the SSL Addition building, to oor. Analyses Performed as taken to Room 140 and visual ic components including solder as then taken to Davin Larson are any deviations from previous	the Silver building to the aced on top of their two do the binders shifted slightly at to Determine Cause by the binders of the Cause by the binders of the binders shifted slightly inspected for any possiconnections. None was Object Thomas Moreau to do to test results. None were object to the binder of the bi	e ble damage to the board, the oserved. horough electrical testing to
		tion/ Resolution	
Larson, has determin rework required for t Transport p Electronic Assemblie	nctions just as it had prior to the ed that no damage has occurred he unit. rocedures have been adopted that es will be placed into a padded/c ies but also between rooms.	to the SEA S/N 016 - 021 t will cover all flight elect	unit. There is no repair or ronic assemblies. All Flight
	; N		
PM: Peter Harvey; Co		ognizant Engineer	

Date of Closure_