



---

**PFR-112 Title: ESA HV Script Problem**

<b>Assembly :</b> GSE	<b>SubAssembly :</b> Scripts	
<b>Component :</b> ESA Scripts	<b>Units Affected:</b>	<b>Units fixed:</b>
<b>Originator:</b> Michael Ludlam	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
<b>Organization:</b> UCB	<b>Date:</b> 20/OCT/05	
<b>Phone:</b> (510) 642 7732	<b>Email :</b> mludlam@ssl.berkeley.edu	

**Failure Occurred During (Check one √)**

☒ Functional test   ☐ Qualification test   ☐ S/C Integration   ☐ Launch operations   ☐ Other (Flight Assy)

**Environment when failure occurred:**

☒ Ambient                      ☐ Vibration                      ☐ Shock                      ☐ Acoustic  
☐ Thermal                      ☐ Vacuum                      ☐ Thermal-Vacuum                      ☐ EMI/EMC

<b>Problem Description</b>
----------------------------

During the ESA\_HV\_CPT on FM1 when the High Voltage was turned on to low levels it was noticed that the HV supply was sweeping the ESA Anodes when it should not have been. Further more the sweep levels were set higher than the raw sweep HV supplies. This would have caused the optocouplers to be operated in a non-nominal configuration such that they were being overdriven.

<b>Analyses Performed to Determine Cause</b>
--

Analysis of the GSE scripts showed that the ESA Pulser test is run prior to the ESA\_HV\_CPT. This sends sweep commands to the ESA to vary the pulser rate. At the end of the test the ESA Actels are not re-initialized to the zero sweep state and so when the raw HV supply reached the threshold of 1kV and the actel sweep outputs were enabled the optocouplers would have been overdriven. The manufacturer of the optocouplers was consulted and it was determined that for the short period when the optocouplers were overdriven that would not have caused any detriment to the parts.

<b>Corrective Action/ Resolution</b>
--------------------------------------

The scripts were changed to re-initialize the ESA Actels with the 6A00 command at the end of the pulser script and to again re-initialize the ESAs at the start of the ESA\_HV\_CPT. All other ESA scripts were checked and no similar problems were found. This PFR is closed.

Acceptance:

MAM: Ron Jackson \_\_\_\_\_; MSE: Ellen Taylor \_\_\_\_\_

PM: Peter Harvey \_\_\_\_\_; Cognizant Engineer \_\_\_\_\_

Date of Closure \_\_\_\_\_