

## PFR-129 Title: Probe Bus Time Jitter

| Assembly : Probe 2                              |  | SubAssembly : BAU            |                         |
|---|--|------------------------------|-------------------------|
| Component : D                                   | PM   |                              |                         |
| Originator: P Harvey                            |  | Organization: UCB            |                         |
| Phone : 510-642-0643                            |  | Email : prh@ssl.berkeley.edu |                         |
| <b>Failure Occurre</b>                          | d During (Check one √)<br>□ Qualification test | $\sqrt{S/C}$ Integration     | □ Launch operations     |
| <b>Environment wh</b><br>√ Ambient<br>□ Thermal | en failure occurred:<br>Vibration<br>Vacuum    | □ Shock<br>□ Thermal-Vacuum  | □ Acoustic<br>□ EMI/EMC |

## **Problem Description**

The spacecraft sends the UTC to the IDPU every second in a 6-byte format as defined in the ICD thm\_sys\_101\_AD section 4.4.1.1.1:

"The Time field is the probe clock time in UTC (4 bytes plus 2 bytes of sub seconds) at the time of the next 1Hz clock tick. This is ordered MSB first."

The IDPU makes a copy of this time and includes it in the APID 404 mnemonic "ONESECMARK." Plots of this data show that there is a <u>substantial variation</u> in the reported time of the next clock tick, while data taken on the interface line "BUS1HZ\_P" shows that the 1-Hz tick has a regular 1.000 second period.

As this time is used by the IDPU to time-tag all its science data, this clock jitter introduces errors in the timing of all E-field and B-Field data points.

## **Analyses Performed to Determine Cause**

Data from APID 404 was plotted to determine the Time Field stability and found that the Time Field has a variability of +/-20 milliseconds.

## **Corrective Action/ Resolution**

This PFR was fixed with Build 3 of the BAU FSW. At UCB, the PFR was officially closed per THM-MINT-PROC-101 F2 PFR Close-out Procedure on 3/2/06. The ONESECMARK telemetry showed minimal variation (within specification) in the reported time of the next clock tick. See plot attached to asrun procedure.

| Acceptance:      |                      |  |
|------------------|----------------------|--|
| MAM: Ron Jackson | ; MSE: Ellen Taylor  |  |
| PM Peter Harvey  | ; Cognizant Engineer |  |
| Date of Closure  |                      |  |





**Figure 1. Plot of Time Field (Byte-by-byte)** Bytes#0-#3 (seconds) = [Violet, Dk Blue, Lt Blue, Green] Bytes#4-#5 (subseconds) = [Yellow, Red ]

The plot shows seconds (green) advancing 1 second per second as expected. The subseconds (Yellow and Red) are expected to stay nearly constant from 1 second to the next, yet vary by approximately  $\pm/-20$  milliseconds.



**Figure 2. Expanded Plot of Time Field (Byte-by-byte)** Bytes#0-#3 (seconds) = [Violet, Dk Blue, Lt Blue, Green] Bytes#4-#5 (subseconds) = [Yellow, Red ]

The plot shows expanded subseconds (Yellow) go from 220 to 226, each of 1/256<sup>th</sup> of a second making a an apparent 23 msec jitter in the science data.