

## Problem/Failure Report THM\_PFR\_131 IDPU Rejects all commands

PFR-131 Title: FM2 IDPU rejects all commands			
Assembly: FM2 IDPU		SubAssembly:	
Component:		Units Affected:	Units fixed:
Originator: Corinna Chen		0 x 0 0 0 0	0 x 0 0 0 0
Organization: UCB SSL Themis		Date: January 23, 2006	
Phone: 510.642.8030		Email: corinnac@ssl.berkeley.edu	
Failure Occurre	ed During (Check one $\sqrt{}$		•
√ Functional test □	☐ Qualification test ☐ S/C Integra	ation   Launch operations	□ Other (Flight Assy)
<b>Environment w</b>	hen failure occurred:		
√ Ambient	□ Vibration		□ Acoustic
□ Thermal	□ Vacuum		□ EMI/EMC
Problem Description			
On January 3, 2006 22:51:40 UTC, the IDPU error counter starts to increment sometime during the ESA mask function at line $\sim$ 60.			
At that point in time, the commands executed counter on the IDPU stopped incrementing when the ESA functional script would continue. The error counter would increment by one each time a command was sent. The error code was wrong command header.  Shortly after, all commands sent would increment the error counter. When raw commands were sent, the error counter incremented. IDPU suddenly goes to safe mode. No commands were getting through.			
Command and error counter did not increment. Since the IDPU would not receive any commands, the IDPU was power cycled.			
Analyses Performed to Determine Cause			
	OM program, FM2 unit had DMA ght software, even the command	A contention issues. During	
Corrective Action/ Resolution			
The solution is to solve the DMA contention problem in PFR127 and repeat the ESA tests.			
Acceptance: MAM: Ron Jackson	ı; N	ISE: Ellen Taylor	
PM: Peter Harvey_	; C	ognizant Engineer	
Date of Closure			