

PFR 150-Sun Sensor Baffle Chipping Title:			
Assembly : Probe	SubAssembly : Sun Sensor		
Component : Baffle	<b>Units Affected:</b>	Units fixed:	
Originator: Paul Turin	2 3 4 5 0	000000	
Organization: SSL	Date: 3/05/2006		
Phone:510-642-5289 Email :pturin@ssl.berkeley.edu		berkeley.edu	
Failure Occurred During (Check one $$ )   □ Functional test □ Qualification test □ S/C Integration □ Launch operations X Other (Flight Assy)			
Environment when failure occurred:			
□ Ambient □ Vibration	□ Shock	□ Acoustic	
$\Box$ Thermal $\Box$ Vacuum	Thermal-Vacuum	□ EMI/EMC	
Problem Description			

During incoming inspection it was noted that both sun sensor baffles had chips in the Z307 black paint applied to the scalloped baffle protrusions. IN addition, the painted edges were slightly polished in spots making them more reflective than the undisturbed paint. The chips expose reflective metal that could allow glint to enter the sun sensor.

## Analyses Performed to Determine Cause

The baffles were shipped together from the vendor in a single bag, allowing the baffles to rub against each other and chip and polish the paint.

## **Corrective Action/ Resolution**

Future shipments should include individual wrapping of the baffles with a nonabrasive paddingand separate bagging to prevent contact.

Acceptance:	
MAM: Ron Jackson	; MSE: Ellen Taylor
PM: Peter Harvey	: Cognizant Engineer



Date of Closure\_\_\_\_\_