

PFR-167 Title:Repeated command destination port closings, ITOS 703p1-5				
Assembly : EGSE		SubAssembly : ITOS		
Component :		Units Affected:	Units fixed:	
Originator: Bryce Roberts		000000	000000	
Organization: UC Berkeley		Date: 21 April 2006		
Phone : (510) 643-4077		Email : broberts@ssl.berkeley.edu		
Failure Occurred During (Check one $$)				
\Box Functional test \Box Qualification test X S/C Integration \Box Launch operations \Box Other (Flight Assy)				
Environment when failure occurred:				
□ Ambient	\Box Vibration		□ Shock	□ Acoustic
Thermal	Vacuum		Thermal-Vacuum	□ EMI/EMC
Problem Description				

(In this section it is important to document the specific symptoms of the problem. In the event we see it happen again, we would like to know as much as possible.)

After upgrading xenon (the EGSE ITOS workstation) to ITOS version 703p1-5, we ran into repeatedly closed connections when we tried to enable commanding to port 29093 (the default port to communicate with the EGSE cmd_decoder). We subsequently discovered that if we temporarily set the command port to 29090, enabled commanding, and then switched back to port 29093, the connection wouldn't close and commands would go through (with good cmd_decoder echoes). This gives us a work-around, but it would be nice to fix this once and for all.

Analyses Performed to Determine Cause

(*How do we know how the failure happened? Was it a bad part, bad handling, what?*) The ITOS log file documents the problem:

16 06-056-20:11:06 STOL_ECHO: Interactive: enable cmd 17 06-056-20:11:06 STOL_MSG: Enabling the cmd subsystem 17 06-056-20:11:06 STOL_MSG: Enabling commands...(cmd host = (null) 11 06-056-20:11:06 CMD_MSG: cmd_transmit connected to localhost (127.0.0.1), port 29093, from localhost (127.0.0.1), port 59095 11 06-056-20:11:06 CMD_MSG: cmd_transmit: Listening for FOP connections on port 7500 11 06-056-20:11:06 CMD_MSG: cmd_transmit (main): EOF on command output port 29093 (fd 6). 11 06-056-20:11:06 CMD_MSG: cmd_transmit: Connection to Command Destination Host localhost on port 29093 closed

Corrective Action/ Resolution

(How do we fix the unit? And how do we make sure it doesn't happen again?)

We've decided to live with this, since there is an easy work-around, the problem is specific to our EGSE racks (we don't have this problem making command connections in the MOC or elsewhere), and as such will be a limited lifetime problem. This PFR can be closed.

Acceptance: MAM: Ron Jackson_____; MSE: Ellen Taylor_____ PM: Peter Harvey______; Cognizant Engineer_____

Date of Closure