

## PFR-178 Title:VC1 Data Packets missing 4 byte CLCW

Assembly : FSW		SubAssembly :	
Component :		<b>Units Affected:</b>	Units fixed:
Originator: Ellen Taylor		X	X
Organization: Swales/UCB		Date: 5/3/06	
<b>Phone:</b> (510) 643-4054		Email : ertaylor@ssl.berkeley.edu	
<b>Failure Occurred During (Check one</b> $$ )			
$\Box$ Functional test $\Box$ Qualification test $\Box$ S/C Integration $\Box$ Launch operations $\sqrt{\text{Other (Flight Assy)}}$			
Environment when failure occurred:			
√ Ambient	□ Vibration	□ Shock	
□ Thermal	Vacuum	Thermal-Vacuum	□ EMI/EMC
Problem Description			

Packet length errors were logged on VC1 data from Probe 4 electrical testing.

## **Analyses Performed to Determine Cause**

Paraphrased from Jim Lewis e-mails 5/9/06 and 5/10/06, Subject: VC1 telemetry problems:

The most recent (yesterday, day 130) data set looks like we a problem with VC1. Packets that are split across transfer frame boundaries are coming up 4 bytes short. The errors represent a packet that is 4 bytes shorter than advertised. (e.g. if datalen-1 = 87, the primary header is 6 bytes, and no secondary header is present, then the total packet length is 87 + 1 + 6 = 94 bytes, but only 90 bytes were inserted into the telemetry stream). First guess is that the 4-byte CLCW at the end of the frame is not accounted for.

## **Corrective Action/ Resolution**

This issue has been sent to Hammers and Swales for further investigation.

Update 6/10/06: CLCW was added to VC1 data packets in FSW V3.12. This version of FSW was delivered with Probe 1 on May 29, 2006 and VC1 data files were confirmed to contain the appropriate CLCW.

Acceptance:	
MAM: Ron Jackson	; MSE: Ellen Taylor

PM: Peter Harvey\_\_\_\_\_; Cognizant Engineer\_\_\_\_\_

Date of Closure\_\_\_\_\_