

PFR-223 Title: RCS Inhibit Status incorrect on EGSE				
Assembly : PCA EGSE		SubAssembly : C	SubAssembly : Cable	
Component :		Units Affected:	Units fixed:	
Originator: Ellen Taylor				
Organization: UCB		Date: 8/16/06 (da	Date: 8/16/06 (date found)	
Phone: (510) 643-4054		Email : ertaylor@	Email : ertaylor@ssl.berkeley.edu	
Failure Occurred During (Check one $$)				
$\sqrt{\text{Functional test}}$ \Box Qualification test \Box S/C Integration \Box Launch operations \Box Other (Flight Assy)				
Environment when failure occurred:				
√ Ambient	\Box Vibration	□ Shock	□ Acoustic	
Thermal	Vacuum	Thermal-Vacuum	□ EMI/EMC	
Problem Description				

(See S. Harris e-mail; Subject: PCA EGSE status; Date: 8/18/06)

On 8/18/06, a PCA EGSE safe-to-mate was run on all five probes. One anomaly was encountered.

Anomaly: On P1, "RCS Inh Status", the voltage measured between pins 43 and 63 measured 0.0V, instead of 2.5V. As a result, P1 was left disconnected, with a note saying that it did not pass safe-to-mate.

Analyses Performed to Determine Cause

(See C. Scholz e-mail; Subject: Re: PCA EGSE status; Date: 8/22/06)

On 8/22/06, Chris Scholz inspected the harness and connectors and determined a broken wire at the feed thru connector, soldered. A new short length of wire into the solder cup and then solder to the end of the broken wire and covered with shrink tubing. Retesting of the connections showed a resistance reading of approximately 2 ohms between pin 43 on the 78 pin connector and pin 3 on the PCA connector and also 2 ohms between pin 63 on the 78 pin connector and pin 31 on the PCA connector.

Corrective Action/ Resolution

On 8/30/06, the PCA EGSE to Probe 1 Safe-to-Mate was completed. The harness fix was verified and Probe 1 connected.

Acceptance: MAM: Ron Jackson_____; MSE: Ellen Taylor_____

PM: Peter Harvey_____; Cognizant Engineer_____

Date of Closure_____