

PFR-224 Title: SCM MagBoom did not deploy during post-env. CPT

| Assembly : Mag Booms | SubAssembly : SCM | |
|--|-----------------------------------|--|
| Component : Frangi-bolt | Units Affected: Units fixed: | |
| Originator: Ellen Taylor | | |
| Organization: UCB | Date: 8/16/06 (date found) | |
| Phone: (510) 643-4054 | Email : ertaylor@ssl.berkeley.edu | |
| Failure Occurred During (Check one $$) | | |
| $\sqrt{\text{Functional test}}$ \Box Qualification test \Box S/C Integration \Box Launch operations \Box Other (Flight Assy) | | |
| Environment when failure occurred: | | |
| $\sqrt{\text{Ambient}}$ \Box Vibration | □ Shock □ Acoustic | |
| \Box Thermal \Box Vacuum | Thermal-Vacuum EMI/EMC | |
| Problem Description | | |

The FGM and SCM Magnetometer Booms on all Probes were fired as part of the post-environmental CPTs. On F2, the FGM Mag Boom frangibolt broke in \sim 25 seconds, but the SCM frangibolt did not break before power was removed by the FSW safety cut-off of 40 seconds. Current drawn during the actuation was 1.45A, less than the 2A +/-10% that was expected.

Analyses Performed to Determine Cause

Inspection of the SCM wiring showed that two pins were miss-wired causing the current to go through only one of the heating elements, not both. The frangi-bolts had been replaced and re-wired after being over-temp'd in the F2 Thermal Vacuum test. A closer look at a 2-second test run after the replacement showed that the current draw in that test was also low (1.45A).

Corrective Action/ Resolution

The SCM wiring was corrected and the Magnetometer Boom Test was re-run on 8/16/06. For the re-test, the FGM boom was disconnected to reduce the risk of overheating. This time, SCM frangi-bolt successfully broke in ~25 seconds and drew the expected amount of current (0.95A).

| Acceptance: MAM: Ron Jackson | ; MSE: Ellen Taylor |
|---------------------------------|----------------------|
| PM: Peter Harvey | ; Cognizant Engineer |

Date of Closure_____