

PFR-23 Title: IDPU DCB Backplane Bad Connection

ļ-		<u> </u>		
Assembly : DCB sn3 / ETU Backplane		SubAssembly:		
Component: Din96 Connector		FM1 affected FM	FM1 affected FM1 fixed	
Originator: Michael Ludlam		Organization: UCB		
Phone: 642 7732		Email: mludlam@ssl.berkeley.edu		
	d During (Check one $\sqrt{}$	- 0/07		
x Functional test	☐ Qualification test	☐ S/C Integration	☐ Launch operations	
Environment wh	en failure occurred:			
x Ambient		□ Shock	☐ Acoustic	
☐ Thermal	□ Vacuum	☐ Thermal-Vacuum	□ EMI/EMC	
	Problem	Description		
	nportant to document the spection, we would like to know as m		bited the problem. In the event	
PCB not receiving co	mmands using DCB SN3 Flig	ht board with ETU backp	lane board.	
		ed to Determine Cau		
(How do we know ho	w the failure happened? Was i	t a bad part, bad handlin	g, what?)	
backplane. The proble continuity between pro-	connection between DCB 96p em was temporary, so during a ins and the board) the problem ith the DCB (Flight) or the Bac	inalyses (demating the co went away. Consequently	nnector and measuring	
	Corrective A	ction/ Resolution		
(How do we fix the un	nit? And how do we make sure	it doesn't happen again?)	
DCB should be left a should be replaced.	as been working well with the sis, if the problem returns, even IDPU Assembled and successes. 19MAY05. MML	en temporarily, then the D	OCB backplane connector	
Acceptance: MAM: Ron Jackson	;	MSE: Ellen Tavlor		
Date of Closure	······································	· · · · · · · · · · · · · · · · · · ·		

thm_PFR_23-1.doc Page 1 of 1