

SMEX


FAST MISSION

IDPU to FAST Spacecraft Integration Procedure


Revision E  
31 January 1994

APPROVED BY: NAME


DATE

  
Peter Harvey  
UCB FAST Software Manager


28 Jan 94

  
Henry Heetderks  
UCB FAST Project Manager

27 JAN 94

  
Dave Everett  
GSFC FAST Electrical System Engineer

1/27/94

  
Ron Kolecki  
GSFC FAST Flight Assurance Manager

1/28/94

## TEST EQUIPMENT LIST

[illegible]

## SUMMARY

This procedure is intended to be used for the initial electrical tests of the FAST IDPU following installation into the FAST spacecraft. It verifies that all required instrument connections are made in the spacecraft wiring harness, checks for most inadvertant cross connections involving power and ground lines, checks most inadvertant connections on data and signal lines, verifies proper operation of the IDPU-MUE interface, and verifies the basic operation of the payload data system portion of the IDPU electronics.

## GENERAL NOTES

- 1) All voltage and resistance measurements are made with respect to spacecraft ground unless otherwise specified.
- 2) Measurements of resistance are made with an approved Digital Multimeter.

## PROCEDURE PART 1 -- Check out and mating of connectors to IDPU

- 1) Notify Q.A. of intent to do test.  
Verify that connector mate/de-mate log is in place.
- 2) Mate P1, P4, and P8 connectors with break-out boxes. Record in log. All shunts out. Verify that pyro shorting plug is installed. Install breakout boxes in harness side only of connectors P3, P5, P6, P7, P9, P10, P11, P12, P13, P14, P19, P22, P23, and P26.
- 3) Resistance measurements made with spacecraft not powered:
  - A) Connector P1:
    - 1) On the S/C side of the connector, verify less than 1 ohm to S/C ground on pins 17, 18, 19, 20, 21, 22, and 26.
    - 2) On the IDPU side of the connector, make the following resistance measurements:
      - a) Using a DMM with the red probe connected to pin 2, measure and record resistance between pins 2 and 17:  
\_\_\_\_\_ (Greater than 20 ohms)
      - b) Using a DMM with the red probe connected to pin 3, measure and record resistance between pins 3 and 18:  
\_\_\_\_\_ (Greater than 20 ohms)
      - c) Using a DMM with the red probe connected to pin 4, measure and record the resistance between pins 4 and 19:  
\_\_\_\_\_ (Greater than 20 ohms)

d) Using a DMM with the red probe connected to pin 5, measure and record resistance between pins 5 and 20:

\_\_\_\_\_ (Greater than 20 ohms)

e) Using a DMM with the red probe connected to pin 6, measure and record resistance between pins 6 and 21:

\_\_\_\_\_ (Greater than 20 ohms)

f) Using a DMM with the red probe connected to pin 7, measure and record resistance between pins 7 and 22:

\_\_\_\_\_ (Greater than 20 ohms)

g) Measure and record the resistance between pins 25, and pin 26.

\_\_\_\_\_ (Approx 10K ohms)

B) On connector P4:

1) On the S/C side of the connector:

a) Verify less than 1 ohm to S/C ground on pins 1, 13, and 15.

b) With the black probe of the ohmmeter connected to S/C ground, on the S/C side of the connector, verify greater than 10 megohm to S/C ground on pins 5, 6, 7, and 8.

2) On the IDPU side of the connector:

a) Verify less than 1 ohm to S/C ground on pins 6, 7, and 15.

b) With the black probe connected to S/C ground, verify greater than 10 Meg ohms resistance to S/C ground on pins 1, 13, and 5.

c) With the black probe of a DMM connected to pin 15, measure and record the resistance to each of the following pins:

3	T/MCLK	_____	(>1K)
4	PIPPER	_____	(>1K)
9	EARTH/SPACE	_____	(>1K)
10	SPACE/EARTH	_____	(>1K)
11	1HZ	_____	(>1K)
12	S/CCLK	_____	(>1K)
14	T/MDAT	_____	(>1K)

C) On connector P8:

1) On the S/C side of the connector:

a) Verify less than 1 ohm to S/C ground on pins 9, 11, and 13.

b) With the black probe of the ohmmeter connected to S/C ground, verify greater than 10 megohm to S/C ground on pins 1, 3, 4, 6, and 8.

2) On the IDPU side of the connector:

a) Verify less than 1 ohm to S/C ground on pins 4, 6, and 13.

- b) With the black probe of the ohmmeter connected to S/C ground, verify greater than 10 megohm to S/C ground on pins 1, 3, 8, 9, and 11.
- D) Make the following measurements on the S/C side of the indicated connectors:
  - 1) With the black probe connected to S/C ground, verify greater than 10 Megohms to S/C ground on all pins of connectors P3, P5, P6, P7, P9, P10, P11, P12, P13, P14, P19, P22, P23, and P26.
  - 2) On connectors P5, P6, P7, P9, and P10, verify less than 1 ohm resistance between the following pins:
    - P5-22 to P9-1
    - P6-22 to P9-2 to P9-3 to P10-11 to P10-12 to P7-22 to P9-4 to P9-5 to P10-24 to P10-25
    - P5-1 to P5-9
    - P5-23 to P5-24
    - P6-1 to P6-9
    - P6-23 to P6-24
    - P7-1 to P7-9
    - P7-23 to P7-24
    - P6-12 to P6-13
    - P7-12 to P7-13
- 3A) Remove break out box from P3 and mate P3 to J3 on the IDPU. Record in mate/de-mate log.
- 4) Power up spacecraft and transition to normal mode.
- 5) Make the following voltage measurements on the S/C side of connector P1:
  - A) Verify all space craft controlled instrument power services are off.
  - B) Verify voltage wrt S/C ground of all pins is between 0 and .10 volts, except pin 25 is between 0 and 5 volts.
  - C) Turn on spacecraft IDPU Power Service A:  
/IDPUAPWR ON
  - D) Verify voltage between +24 and +32 volts wrt S/C ground on pin 2, record.
  - E) Verify between 0 and .10 volts wrt S/C ground on pins 3, 4, 5, 6, and 7.
  - F) Turn on spacecraft IDPU Power Service B:  
/IDPUBPWR ON
  - G) Verify voltage between +24 and +32 volts on pin 3. \_\_\_\_\_
  - H) Verify between 0 and .10 volts wrt S/C ground on pins 4, 5, 6, and 7.
  - I) Turn on spacecraft Instrument Power Service A:  
/INSTRAPWR ON
  - J) Verify voltage between +24 and +32 volts on pin 4. \_\_\_\_\_
  - K) Verify between 0 and .10 volts wrt S/C ground on pins 5, 6, and 7.
  - L) Turn on spacecraft Instrument Power Service B:  
/INSTRBPWR ON

- M) Verify voltage between +24 and +32 volts on pin 5. \_\_\_\_\_
  - N) Verify between 0 and .10 volts wrt S/C ground on pins 6 and 7.
  - O) Turn on spacecraft Motor Power Service:  
/IWBOOMPWR ON
  - P) Verify voltage between +24 and +32 volts on pins 6 and 7. \_\_\_\_\_
  - Q) Turn off Instrument A and Motor spacecraft power services:  
/IWBOOMPWR OFF  
/INSTRAPWR OFF
  - R) Verify between 0 and .10 volts wrt S/C ground on pins 6, 7, and 4.
  - S) Turn off Instrument B power service:  
/INSTRBPWR OFF
  - T) Verify between 0 and .10 volts wrt S/C ground on pin 5.
  - U) Turn off IDPU A power service:  
/IDPUAPWR OFF
  - V) Verify between 0 and .10 volts wrt S/C ground on pin 2.
  - W) Turn off IDPU B power service:  
/IDPUBPWR OFF
  - X) Verify between 0 and .10 volts wrt S/C ground on pins 2, 3, 4, 5, 6 and 7.
- 6) Perform the following measurements of the IDPU currents:
- A) Install shunt in P1 pin 17. Install ammeter in series with P1 pin 2 and set for 1 amp full scale.
  - B) Turn on IDPU A power:  
/IDPUAPWR ON
  - C) Measure and record the current measured: \_\_\_\_\_  
(180 +/- 50 mA)
  - D) Record IDPU current from TCW display: \_\_\_\_\_
  - E) Turn off IDPU power:  
/IDPUAPWR OFF  
verify current is zero
  - F) Remove ammeter from P1 pin 2. Install shunts in P1 pins 2, 3, 18 and 19. Install ammeter in series with P1 pin 4 and set for 1 amp full scale.
  - G) Turn on IDPU B and Instrument A power:  
/IDPUBPWR ON  
/INSTRAPWR ON
  - H) Measure and record the current measured: \_\_\_\_\_
  - I) Record IDPU and instrument current from TCW display:  
IDPU \_\_\_\_\_ Instrument \_\_\_\_\_

- J) Turn off IDPU B and Instrument A power:  
       /IDPUBPWR OFF  
       verify  
       /INSTRAPWR OFF  
       verify
- K) Remove ammeter and install all remaining shunts in connector.
- 7) Make the following measurements on S/C side of connector P4:
- A) Turn on MUE Port B:  
       /S900KTLM
- B) Stimulate HCI and Sun Sensor with MUE GSE.
- C) Use oscilloscope to verify logic outputs as listed below:
- |    |                          |
|----|--------------------------|
| 2  | T/MREQ                   |
| 3  | T/MCLK                   |
| 4  | PIPPER                   |
| 9  | EARTH/SPACE              |
| 10 | SPACE/EARTH              |
| 11 | 1HZ                      |
| 12 | 2**22 HZ (about 4.2 MHz) |
- D) Use oscilloscope to verify less than .1 volts on input T/MDATA on pin 14.
- E) Return to 4k telemetry: /s4ktlm
- 8) Make the following measurements on the S/C side of connector P8:
- A) Turn on MUE Port A:  
       /IDPUAPWR ON
- B) Use oscilloscope to verify logic outputs listed below:
- |    |                     |
|----|---------------------|
| 2  | Data A, MUE to IDPU |
| 10 | Data B, MUE to IDPU |
- C) Send commands to set IDPU level commands low:  
       /IDPURESET OPERATE  
       /IDPUROMSEL BANK0  
       /IDPUARTSEL LOW
- D) Use oscilloscope to verify the following. Record the value as read from the scope screen in the space provided:
- |    |                                 |       |       |
|----|---------------------------------|-------|-------|
| 7  | Reset, MUE to IDPU cpu          | (low) | _____ |
| 14 | IDPUROM Select, MUE to IDPU cpu | (low) | _____ |
| 15 | IDPUART Select, MUE to IDPU cpu | (low) | _____ |
- E) Send command to set IDPU reset high:  
       /IDPURESET RESET
- F) Use oscilloscope to verify the following. Record the value as read from the scope screen in the space provided:
- |    |                                 |        |       |
|----|---------------------------------|--------|-------|
| 7  | Reset, MUE to IDPU cpu          | (high) | _____ |
| 14 | IDPUROM Select, MUE to IDPU cpu | (low)  | _____ |
| 15 | IDPUART Select, MUE to IDPU cpu | (low)  | _____ |



- G) Send commands to set the IDPU reset low and PROM select to bank 1:  
       /IDPURESET OPERATE  
       /IDPUROMSEL BANK1
- H) Use oscilloscope to verify the following. Record the value as read from the scope screen in the space provided:  
       7 Reset, MUE to IDPU cpu (low) \_\_\_\_\_  
       14 IDPUROM Select, MUE to IDPU cpu(high) \_\_\_\_\_  
       15 IDPUART Select, MUE to IDPU cpu(low) \_\_\_\_\_
- I) Send commands to set the IDPU ROM to bank 0 and the UART select to high:  
       /IDPUROMSEL BANK0  
       /IDPUARTSEL HIGH
- J) Use oscilloscope to verify the following. Record the value as read from the scope screen in the space provided:  
       7 Reset, MUE to IDPU cpu (low) \_\_\_\_\_  
       14 IDPUROM Select, MUE to IDPU cpu(low) \_\_\_\_\_  
       15 IDPUART Select, MUE to IDPU cpu(high) \_\_\_\_\_
- K) Send the command to set the IDPU UART select low:  
       /IDPUARTSEL LOW
- L) Use the oscilloscope to verify less than .1 volts on the logic inputs listed below:  
       5 Data A, IDPU to MUE  
       12 Data B, IDPU to MUE
- 9) Make the following measurements on the IDPU side of connector P8:  
 A) Turn on IDPU and Instrument power:  
       /IDPUAPWR ON  
       /INSTRAPWR ON  
 B) Use the oscilloscope to verify the logic signals listed below:  
       5 Data A, IDPU to MUE  
       12 Data B, IDPU to MUE  
 C) Use the oscilloscope to verify less than .1 volts on the input lines listed below:  
       2 Data A, MUE to IDPU  
       7 Reset, MUE to IDPU Processor  
       10 Data B, MUE to IDPU  
       14 IDPUROM Sel, MUE to IDPU Proc  
       15 IDPUART Sel, MUE to IDPU Proc
- 10) Power down spacecraft.
- 11) Remove break-out boxes from connectors P1, P4, and P8 and mate connectors, installing UCB Dwg. A0131 Port B Passive Tap Assembly in series with connector P4. Mate A0131 to UCB GSE System using 50-foot DA15 extension cable. Install breakout boxes in harness side only. Record all connector mates and de-mates in log.
- 12) Power up spacecraft.

- 13) Run SHOMON2 on UCB SOC. Turn on IPDU power:
  - /IDPUAPWR ON
  - /IDPUBPWR ON
  - /INSTRAPWR ON
  - /INSTRBPWR ON
 Record total current monitor on SOC: \_\_\_\_\_ (240 +/- 50 mA)  
 SHOVAL PNEBCURR \_\_\_\_\_ (240 +/- 50 mA)
- 14) Perform check of IDPU functions by running STOL procedure IDPUCHECK. (Leaves IDPU powered off when complete.)
- 15) Connect breakout boxes to harness side only of connectors P15, P16A, and P16B.
- 16) Turn on all instrument power services:
  - /IDPUAPWR ON
  - /INSTRAPWR ON
  - /IWBOOMPWR ON
- 17) Turn on all instrument controlled +28 volt power services:
  - /IPWRLEVEL 3
  - /ICDI VALUE=H'xxxxxx' (ESA HV enable code 1)
  - /ICDI VALUE=H'yyyyyy' (ESA HV enable code 2)
  - /ICDI VALUE=H'F8FFFF' (All services on)
  - /ICDI VALUE=H'F9FFFF' (All services on)
- 18) Record current readings below:
 

TCW Monitors:	UCB SOC Monitors:
IDPUCURR _____	MCMON1 _____
INSTRCURR _____	MCMON2 _____
IWBOOMCURR _____	MCMON3 _____
- 19) Print page of SHOMON2 on UCB SOC.
- 20) Use oscilloscope to verify voltage on all pins of connectors P5, P6, P7, P9, P10, P11, P12, P13, P14, P19, P22, P23, and P26 is less than .1 volts.
- 21) Use oscilloscope to verify voltage on all pins of 15, P16A, and P16B. Verify all values are less than .1 volts, except those listed below. For those listed, record value.
 

P15-11 _____	(+21 to +32 volts)
P15-13 _____	(+21 to +32 volts)
P16A-11 _____	(+21 to +32 volts)
P16A-12 _____	(+21 to +32 volts)
P16B-11 _____	(+21 to +32 volts)
P16B-12 _____	(+21 to +32 volts)
- 22) Turn off all IDPU, Instrument, and Motor power:
  - /IWBOOMPWR OFF
  - /INSTRAPWR OFF
  - /INSTRBPWR OFF
  - /IDPUAPWR OFF
  - /IDPUBPWR OFF

- 23) Demate breakout boxes from connectors P15, P16A, and P16B.  
Connect breakout boxes to connectors P16C, and P16D.
- 24) Use oscilloscope to verify voltage on all pins of P16C, P16D, P17A, P17B, P17C, P17D, and P21. Verify all values are less than .1 volts, except those listed below. For those listed, record value.
- |         |       |                    |
|---------|-------|--------------------|
| P16C-11 | _____ | (+21 to +32 volts) |
| P16C-12 | _____ | (+21 to +32 volts) |
| P16D-11 | _____ | (+21 to +32 volts) |
| P16D-12 | _____ | (+21 to +32 volts) |
| P17A-1  | _____ | (+21 to +32 volts) |
| P17A-2  | _____ | (+21 to +32 volts) |
| P17B-1  | _____ | (+21 to +32 volts) |
| P17B-2  | _____ | (+21 to +32 volts) |
| P17C-1  | _____ | (+21 to +32 volts) |
| P17C-2  | _____ | (+21 to +32 volts) |
| P17D-1  | _____ | (+21 to +32 volts) |
| P17D-2  | _____ | (+21 to +32 volts) |
| P21-1   | _____ | (+21 to +32 volts) |
- 25) Mate connectors P5, P6, P7, P9, P10, P11, P12, P13, and P14, and record in log.

## PROCEDURE PART 2 -- Checkout of instrument interface connectors

### RESISTANCE MEASUREMENTS MADE WITH S/C NOT POWERED:

Make the following measurements with a break-out box installed in the harness side of the connectors only.

#### 1) P15 checkout:

- A) With the black probe of the ohmmeter connected to S/C ground, verify greater than 10 megohm to S/C ground on pins 4, 6, 7, 8, 9, 12, 18, 20, 21, 22, and 24.
- B) Verify less than 1 ohm to S/C ground on pins 1, 10, 16, 23, and 25.
- C) With the black ohmmeter probe connected to S/C ground, measure and record the resistance between the following pins and ground:

5	_____	(> 1K )
19	_____	(> 1K )

#### 2) P16A checkout:

- A) Verify greater than 10 megohm to S/C ground on pins 4, 6, 7, 13, 18, 20, 22, and 25.
- B) Verify less than 1 ohm to S/C ground on pins 1, 10, 16, 23, and 24.
- C) With the black ohmmeter probe connected to S/C ground, measure and record the resistance between the following pins and ground:

5	_____	(> 1K )
19	_____	(> 1K )
8	_____	(> 1K )
21	_____	(> 1K )
9	_____	(> 1K )

#### 3) P16B checkout:

- A) Verify greater than 10 megohm to S/C ground on pins 4, 6, 7, 13, 18, 20, 22, and 25.
- B) Verify less than 1 ohm to S/C ground on pins 1, 10, 16, 23, and 24.
- C) With the black ohmmeter probe connected to S/C ground, measure and record the resistance between the following pins and ground:

5	_____	(> 1K )
19	_____	(> 1K )
8	_____	(> 1K )
21	_____	(> 1K )
9	_____	(> 1K )

#### 3) P16C checkout:

- A) Verify greater than 10 megohm to S/C ground on pins 4, 6, 7, 13, 18, 20, 22, and 25.
- B) Verify less than 1 ohm to S/C ground on pins 1, 10, 16, 23, and 24.
- C) With the black ohmmeter probe connected to S/C ground, measure and record the resistance between the following

pins and ground:

5	_____	(> 1K )
19	_____	(> 1K )
8	_____	(> 1K )
21	_____	(> 1K )
9	_____	(> 1K )

4) P16D checkout:

- A) Verify greater than 10 megohm to S/C ground on pins 4, 6, 7, 13, 18, 20, 22, and 25.
- B) Verify less than 1 ohm to S/C ground on pins 1, 10, 16, 23, and 24.
- C) With the black ohmmeter probe connected to S/C ground, measure and record the resistance between the following pins and ground:

5	_____	(> 1K )
19	_____	(> 1K )
8	_____	(> 1K )
21	_____	(> 1K )
9	_____	(> 1K )

5) P17A checkout:

- A) Verify greater than 10 megohm to S/C ground on pins 8 and 15.
- B) Verify less than 1 ohm to S/C ground on pins 3, 6, 9, 10, 11, and 13, 14, and A1 shield and A2 shield.
- C) With the black ohmmeter probe connected to S/C ground, measure and record the resistance between the following pins and ground:

5	_____	(> 1K )
7	_____	(> 1K )
12	_____	(> 1K )
A1	_____	(> 1K )
A2	_____	(> 1K )

6) P17 B checkout:

- A) Verify greater than 10 megohm to S/C ground on pins 8 and 15.
- B) Verify less than 1 ohm to S/C ground on pins 3, 6, 9, 10, 11, and 13, 14, and A1 shield and A2 shield.
- C) With the black ohmmeter probe connected to S/C ground, measure and record the resistance between the following pins and ground:

5	_____	(> 1K )
7	_____	(> 1K )
12	_____	(> 1K )
A1	_____	(> 1K )
A2	_____	(> 1K )

7) P17C checkout:

- A) Verify greater than 10 megohm to S/C ground on pins 8 and 15.

B) Verify less than 1 ohm to S/C ground on pins 3, 6, 9, 10, 11, and 13, 14, and A1 shield and A2 shield.

C) With the black ohmmeter probe connected to S/C ground, measure and record the resistance between the following pins and ground:

5	_____	(> 1K )
7	_____	(> 1K )
12	_____	(> 1K )
A1	_____	(> 1K )
A2	_____	(> 1K )

8) P17D checkout:

A) Verify greater than 10 megohm to S/C ground on pins 8 and 15.

B) Verify less than 1 ohm to S/C ground on pins 3, 6, 9, 10, 11, and 13, 14, and A1 shield and A2 shield.

C) With the black ohmmeter probe connected to S/C ground, measure and record the resistance between the following pins and ground:

5	_____	(> 1K )
7	_____	(> 1K )
12	_____	(> 1K )
A1	_____	(> 1K )
A2	_____	(> 1K )

9) P21 Checkout:

A) Verify greater than 10 megohm to S/C ground on pins 8 and 15.

B) Verify less than 1 ohm to S/C ground on pins 3, 6, 9, 10, 11, and 13, 14, and A1 shield and A2 shield.

C) With the black ohmmeter probe connected to S/C ground, measure and record the resistance between the following pins and ground:

5	_____	(> 1K )
7	_____	(> 1K )
12	_____	(> 1K )
A1	_____	(> 1K )
A2	_____	(> 1K )

10) P22 Checkout:

A) Verify less than 1 ohm to S/C ground on pins 3, 4, 12, 15, 21, 22, 24, 25, and 26.

B) Verify greater than 10 megohm to S/C ground on pins 5, 13, 14, and 23.

11) P23 checkout.

A) Verify less than 1 ohm to S/C ground on pins 14, 16, 18, 19, 25, and 26.

B) Verify greater than 10 megohm to S/C ground on pins 2, 6, 7, 8, 11, 12, 13, 20, and 24.

## MEASUREMENTS MADE WITH SPACECRAFT POWERED

All voltage measurements are made with an oscilloscope and are referenced to S/C ground.

12) Power up spacecraft.

13) Run SHOMON2 on UCB SOC. Turn on IPDU, Instrument, and Motor power services:

/IDPUAPWR ON  
/IDPUBPWR ON  
/INSTRAPWR ON  
/INSTRBPWR ON  
/IWBOOMPWR ON  
/IPWRLEVEL 3

Verify total current drawn by IDPU is 240 +/- 50 mA.

Record current readings below:

TCW Monitors:

IDPUCURR \_\_\_\_\_  
INSTRCURR \_\_\_\_\_  
IWBOOMCURR \_\_\_\_\_

UCB SOC Monitors:

MCMON1 \_\_\_\_\_  
MCMON2 \_\_\_\_\_  
MCMON3 \_\_\_\_\_

14) P15 checkout:

A) Turn on TEAMS only:

/ICDI VALUE=H'F90000'

/ICDI VALUE=H'F80203' (Services 1,2,5 on)

B) Use the oscilloscope to measure and record the voltage to S/C ground on the pins below:

11 \_\_\_\_\_ (Approx +28 Volts)  
13 \_\_\_\_\_ (Approx +28 Volts)

15) P16A checkout:

A) Turn on ESA 1 HV only:

/ICDI VALUE=H'F80403' (Services 1,2,15 on)

B) Use the oscilloscope to measure and record the voltage to S/C ground on the pins below:

11 \_\_\_\_\_ (Approx 0 Volts)  
12 \_\_\_\_\_ (Approx +28 Volts)

C) Turn on ESA 1 LV only:

/ICDI VALUE=H'F80007' (Services 1,2,19 on)

D) Use the oscilloscope to measure and record the voltage to S/C ground on the pins below:

11 \_\_\_\_\_ (Approx +28 Volts)  
12 \_\_\_\_\_ (Approx 0 Volts)

16) P16B checkout:

A) Turn on ESA 2 HV only:

/ICDI VALUE=H'F80803' (Services 1,2,16 on)

B) Use the oscilloscope to measure and record the voltage to S/C ground on the pins below:

11 \_\_\_\_\_ (Approx 0 Volts)  
12 \_\_\_\_\_ (Approx +28 Volts)

- C) Turn on ESA 2 LV only:  
       /ICDI VALUE=H'F8000B' (Services 1,2,20 on)
- D) Use the oscilloscope to measure and record the voltage to  
     S/C ground on the pins below:  
       11 \_\_\_\_\_ (Approx +28 Volts)  
       12 \_\_\_\_\_ (Approx 0 Volts)
- 17) P16C checkout:
- A) Turn on ESA 3 HV only:  
       /ICDI VALUE=H'F81003' (Services 1,2,17 on)
- B) Use the oscilloscope to measure and record the voltage to  
     S/C ground on the pins below:  
       11 \_\_\_\_\_ (Approx 0 Volts)  
       12 \_\_\_\_\_ (Approx +28 Volts)
- C) Turn on ESA 3 LV only:  
       /ICDI VALUE=H'F80013' (Services 1,2,21 on)
- D) Use the oscilloscope to measure and record the voltage to  
     S/C ground on the pins below:  
       11 \_\_\_\_\_ (Approx +28 Volts)  
       12 \_\_\_\_\_ (Approx 0 Volts)
- 18) P16D checkout:
- A) Turn on ESA 4 HV only:  
       /ICDI VALUE=H'F82003' (Services 1,2,18 on)
- B) Use the oscilloscope to measure and record the voltage to  
     S/C ground on the pins below:  
       11 \_\_\_\_\_ (Approx 0 Volts)  
       12 \_\_\_\_\_ (Approx +28 Volts)
- C) Turn on ESA 4 LV only:  
       /ICDI VALUE=H'F80023' (Services 1,2,22 on)
- D) Use the oscilloscope to measure and record the voltage to  
     S/C ground on the pins below:  
       11 \_\_\_\_\_ (Approx +28 Volts)  
       12 \_\_\_\_\_ (Approx 0 Volts)
- 19) P17A and P17B checkout: (Tests done on both connectors.)
- A) Turn on Rad 1 & 2 Motor Power only:  
       /ICDI VALUE=H'F80003' (Services 1,2 on)  
       /ICDI VALUE=H'F90100' (Service 25 on)
- B) Use the oscilloscope to measure and record the voltage to  
     S/C ground on the pins below:  
       P17A-1 \_\_\_\_\_ P17B-1 \_\_\_\_\_ (Approx 0 Volts)  
       P17A-2 \_\_\_\_\_ P17B-2 \_\_\_\_\_ (Approx +28 Volts)
- C) Turn on Radial 1 & 2 LV only:  
       /ICDI VALUE=H'F80043' (Services 1,2,6 on)  
       /ICDI VALUE=H'F90000'
- D) Use the oscilloscope to measure and record the voltage to  
     S/C ground on the pins below:  
       P17A-1 \_\_\_\_\_ P17B-1 \_\_\_\_\_ (Approx +28 Volts)  
       P17A-2 \_\_\_\_\_ P17B-2 \_\_\_\_\_ (Approx 0 Volts)



- 20) P17C and P17D checkout: (Tests done on both connectors.)
- A) Turn on Rad 3 & 4 Motor Power only:  
       /ICDI VALUE=H'F80003' (Services 1,2 on)  
       /ICDI VALUE=H'F90100' (Service 25 on)
- B) Use the oscilloscope to measure and record the voltage to S/C ground on the pins below:  
       P17C-1 \_\_\_\_\_ P17D-1 \_\_\_\_\_ (Approx 0 Volts)  
       P17C-2 \_\_\_\_\_ P17D-2 \_\_\_\_\_ (Approx +28 Volts)
- C) Turn on Radial 1 & 2 LV only:  
       /ICDI VALUE=H'F80043' (Services 1,2,6 on)  
       /ICDI VALUE=H'F90000'
- D) Use the oscilloscope to measure and record the voltage to S/C ground on the pins below:  
       P17C-1 \_\_\_\_\_ P17D-1 \_\_\_\_\_ (Approx +28 Volts)  
       P17C-2 \_\_\_\_\_ P17D-2 \_\_\_\_\_ (Approx 0 Volts)
- 21) P21 checkout:
- A) Turn on Axial Boom LV Power only:  
       /ICDI VALUE=H'F80103' (Services 1,2,24 on)
- B) Use the oscilloscope to measure and record the voltage to S/C ground on the pin below:  
       P21-1 \_\_\_\_\_ (Approx +28 Volts)
- 22) P19 and P26 checkout.
- A) Connect UCB Dwg. No. A0125 Mag Boom Test Panel to P19 and P26. Need 6-foot DE9 extension cable to make connection.
- B) Run SHOMAGSW on UCB SOC.
- C) Press TURNSMAG\_A button on Mag Boom Test Panel.
- D) Hold for two seconds, then release.
- E) In DEPLOY STAT window see LENG7 value increment by two.
- F) Press TURNSMAG\_B button on Mag Boom Test Panel.
- G) Hold for two seconds, then release.
- H) In DEPLOY STAT window see LENG8 value increment by two.
- I) In MON 140 window see MAGLATA value greater than 2.000V.
- J) Press and hold MAGLAT\_A button on Mag Boom Test Panel.
- K) In MON 140 window see MAGLATA value less than 0.300V within one minute.
- L) Release MAGLAT\_A button.
- M) In MON 140 window see MAGLATB value greater than 2.000V.
- N) Press and hold MAGLAT\_B button on Mag Boom Test Panel.
- O) In MON 140 window see MAGLATB value less than 0.300V within one minute.
- P) Release MAGLAT\_B button.

- 23) P22 checkout.
- A) Install ETU Flux gate Magnetometer into connector P22 using 26S-26S gender changer.
  - B) Set up to test Flux Gate Mag by sending commands:
    - /IDPURESET RESET
    - /IDPURESET OPERATE
    - /IPWRLEVEL VALUE=3
    - /ISVCXMIT VC2=1,VC2X=1,VC3=1,VC4=1,VC5=1
    - /ISETBIT ADR=H'F9', BIT=0 (Service 7 on)
    - /ISETBIT ADR=H'F9', BIT=1 (Service 8 on)
    - /ICDI VALUE=H'A80000'
    - /ICDI VALUE=H'800000'
    - /ICDI VALUE=H'827100'
    - /ICDI VALUE=H'D90000'
    - /ICLRBIT ADR=H'D8', BIT=8 (Enable Survey 0)
    - /ICLRBIT ADR=H'D8', BIT=9 (Enable Survey 1)
    - /ICLRBIT ADR=H'D8', BIT=10 (Enable Survey 2)
    - /ISETBIT ADR=H'F8', BIT=14 (Service 4 on)
    - /ISETBIT ADR=H'F8', BIT=15 (Service 3 on)
  - C) Run SHOFLUX on UCB SOC.
  - D) Rotate ETU Magnetometer in Earth's field. Verify appropriate change in display.
- 24) P23 checkout.
- A) Measure and record voltages as listed below:
 

9		(Should be +5 Volts)
15		(Should be +15 Volts)
17		(Should be -15 Volts)
- 25) Turn off all IDPU, Instrument, and Motor power:
- /IWBOOMPWR OFF
  - /INSTRAPWR OFF
  - /INSTRBPWR OFF
  - /IDPUAPWR OFF
  - /IDPUBPWR OFF
- 26) Power down spacecraft.  
Remove ETU Flux Gate Magnetometer.

SMEX

FAST MISSION

IDPU to FAST Spacecraft Integration Procedure

STARTED : 1-28-94

COMPLETED : 1-30-94

By: HENRY HEEDERIK  
TERESA LAFOURCADE

Revision E  
31 January 1994

APPROVED BY: NAME


DATE

  
Peter Harvey  
UCB FAST Software Manager


28 Jan 94

  
Henry Heetderks  
UCB FAST Project Manager

27 JAN 94

  
Dave Everett  
GSFC FAST Electrical System Engineer

1/27/94

  
Ron Kolecki  
GSFC FAST Flight Assurance Manager

1/28/94

## IDPU TO FAST SPACECRAFT ELECTRICAL INTEGRATION PROCEDURE

## TEST EQUIPMENT LIST

ITEM	MAKE/MODEL	I/D NO.	CAL DUE DATE
MULTI-METER	BECKMAN RHS 3020	460431	2 MAR 94
OSCILLOSCOPE	IWATSU SS 6122	189077	2 MAR 94
MAG SWITCH RESISTOR	UCB dury No. A0125	—	—
UCB ETC FLUX GATE MAGNETOMETER	N/A	N/A	N/A

## SUMMARY

This procedure is intended to be used for the initial electrical tests of the FAST IDPU following installation into the FAST spacecraft. It verifies that all required instrument connections are made in the spacecraft wiring harness, checks for most inadvertant cross connections involving power and ground lines, checks most inadvertant connections on data and signal lines, verifies proper operation of the IDPU-MUE interface, and verifies the basic operation of the payload data system portion of the IDPU electronics.

## GENERAL NOTES

- 1) All voltage and resistance measurements are made with respect to spacecraft ground unless otherwise specified.
- 2) Measurements of resistance are made with an approved Digital Multimeter.

## PROCEDURE PART 1 -- Check out and mating of connectors to IDPU

- 1) Notify Q.A. of intent to do test.  
Verify that connector mate/de-mate log is in place.
- 2) Mate P1, P4, and P8 connectors with break-out boxes. Record in log. All shunts out. Verify that pyro shorting plug is installed. Install breakout boxes in harness side only of connectors P3, P5, P6, P7, P9, P10, P11, P12, P13, P14, P19, P22, P23, and P26.
- 3) Resistance measurements made with spacecraft not powered:
  - A) Connector P1:
    - 1) *W* On the S/C side of the connector, verify less than 1 ohm to S/C ground on pins 17, 18, 19, 20, 21, 22, and 26.
    - 2) On the IDPU side of the connector, make the following resistance measurements:
      - a) Using a DMM with the red probe connected to pin 2, measure and record resistance between pins 2 and 17:  
*W* .443 M (Greater than 20 ohms)
      - b) Using a DMM with the red probe connected to pin 3, measure and record resistance between pins 3 and 18:  
*W* .5 M (Greater than 20 ohms)
      - c) Using a DMM with the red probe connected to pin 4, measure and record the resistance between pins 4 and 19:  
*W* .5 M (Greater than 20 ohms)

- d) Using a DMM with the red probe connected to pin 5, measure and record resistance between pins 5 and 20:

~1.5 M (Greater than 20 ohms)

- e) Using a DMM with the red probe connected to pin 6, measure and record resistance between pins 6 and 21:

OL (Greater than 20 ohms)

- f) Using a DMM with the red probe connected to pin 7, measure and record resistance between pins 7 and 22:

OL (Greater than 20 ohms)

- g) Measure and record the resistance between pins 25, and pin 26.

12.56 K (Approx 10K ohms)

B) On connector P4:

- 1) On the S/C side of the connector:

- a) Verify less than 1 ohm to S/C ground on pins 1, 13, and 15. *OK - 2310 on MUE WAS NOT MATED. AFTER MATING P310 MEASUREMENT WAS VERIFIED.*
- b) With the black probe of the ohmmeter connected to S/C ground, on the S/C side of the connector, verify greater than 10 megohm to S/C ground on pins 5, 6, 7, and 8. *OK*

- 2) On the IDPU side of the connector:

- a) Verify less than 1 ohm to S/C ground on pins 6, 7, and 15. *OK - 40H*
- b) With the black probe connected to S/C ground, verify greater than 10 Meg ohms resistance to S/C ground on pins 1, 13, and 5. *OK PINS 1 AND 13 SPUN TO S/C*
- c) With the black probe of a DMM connected to pin 15, measure and record the resistance to each of the following pins: *CERT LOG DISCREP OK*

3	T/MCLK	~1 M	40H	(>1K)
4	PIPPER	~1 M	40H	(>1K)
9	EARTH/SPACE	~1 M	40H	(>1K)
10	SPACE/EARTH	~1 M	40H	(>1K)
11	1HZ	~1 M	40H	(>1K)
12	S/CCLK	~1 M	40H	(>1K)
14	T/MDAT	~20 M	40H	(>1K)

C) On connector P8:

- 1) On the S/C side of the connector:

- a) Verify less than 1 ohm to S/C ground on pins 9, 11, and 13. *OK - 40H*
- b) With the black probe of the ohmmeter connected to S/C ground, verify greater than 10 megohm to S/C ground on pins 1, 3, 4, 6, and 8. *OK OK OK OK OK PINS 4 AND 6 ARE GROUNDED TO S/C*

- 2) On the IDPU side of the connector:

- a) Verify less than 1 ohm to S/C ground on pins 4, 6, and 13. *OK OK OK - 40H CERT LOG DISCREP OK*

checked on S/C:  
P23 is a 265  
P22 is a 26P  
-HDM 28 JAN 94

- b) With the black probe of the ohmmeter connected to S/C ground, verify greater than 10 megohm to S/C ground on pins (1, 3, 8, 9, and 11). -HDM 28 JAN 94

D) Make the following measurements on the S/C side of the indicated connectors:

- 1) With the black probe connected to S/C ground, verify greater than 10 Megohms to S/C ground on all pins of connectors P3, P5, P6, P7, P9, P10, P11, P12, P13, P14, P19, P22, P23, and P26. -HDM 28 JAN 94

- 2) On connectors P5, P6, P7, P9, and P10, verify less than 1 ohm resistance between the following pins:

P5-22 to P9-1

P6-22 to P9-2

P9-3 to P10-11

P10-12 to P7-22

P9-4 to P9-5

P10-24 to P10-25

P5-1 to P5-9

P5-23 to P5-24

P6-1 to P6-9

P6-23 to P6-24

P7-1 to P7-9

P7-23 to P7-24

P6-12 to P6-13

P7-12 to P7-13

- 3) Remove break out box from P3 and mate P3 to J3 on the IDPU. Record in mate/de-mate log.

- 4) Power up spacecraft and transition to normal mode.

- 5) Make the following voltage measurements on the S/C side of connector P1:

✓A) Verify all space craft controlled instrument power services are off.

✓B) Verify voltage wrt S/C ground of all pins is between 0 and .10 volts, except pin 25 is between 0 and 5 volts. 2.5v

✓C) Turn on spacecraft IDPU Power Service A:  
/IDPUAPWR ON

✓D) Verify voltage between +24 and +32 volts wrt S/C ground on pin 2, record. 31.5v

✓E) Verify between 0 and .10 volts wrt S/C ground on pins 3, 4, 5, 6, and 7.

✓F) Turn on spacecraft IDPU Power Service B:  
/IDPUBPWR ON

✓G) Verify voltage between +24 and +32 volts on pin 3. 31.5v

✓H) Verify between 0 and .10 volts wrt S/C ground on pins 4, 5, 6, and 7.

✓I) Turn on spacecraft Instrument Power Service A:  
/INSTRAPWR ON

✓J) Verify voltage between +24 and +32 volts on pin 4. 31.5v

✓K) Verify between 0 and .10 volts wrt S/C ground on pins 5, 6, and 7.

✓L) Turn on spacecraft Instrument Power Service B:  
/INSTRBPWR ON



- ✓M) Verify voltage between +24 and +32 volts on pin 5. 31.5 ✓
- ✓N) Verify between 0 and .10 volts wrt S/C ground on pins 6 and 7.
- ✓O) Turn on spacecraft Motor Power Service:  
/IWBOOMPWR ON
- ✓P) Verify voltage between +24 and +32 volts on pins 6 and 7. 31.5
- ✓Q) Turn off Instrument A and Motor spacecraft power services:  
/IWBOOMPWR OFF  
/INSTRAPWR OFF
- ✓R) Verify between 0 and .10 volts wrt S/C ground on pins 6, 7, and 4.
- ✓S) Turn off Instrument B power service:  
/INSTRBPWR OFF
- ✓T) Verify between 0 and .10 volts wrt S/C ground on pin 5.
- ✓U) Turn off IDPU A power service:  
/IDPUAPWR OFF
- ✓V) Verify between 0 and .10 volts wrt S/C ground on pin 2.
- ✓W) Turn off IDPU B power service:  
/IDPUBPWR OFF
- ✓X) Verify between 0 and .10 volts wrt S/C ground on pins 2, 3, 4, 5, 6 and 7.

6) Perform the following measurements of the IDPU currents:

- ✓A) Install shunt in P1 pin 17. Install ammeter in series with P1 pin 2 and set for 21 amp full scale.
- ✓B) Turn on IDPU A power:  
/IDPUAPWR ON
- ✓C) Measure and record the current measured: 138 mA  
(180 +/- 50 mA)
- ✓D) Record IDPU current from TCW display: 136 mA
- ✓E) Turn off IDPU power:  
/IDPUAPWR OFF  
verify current is zero
- ✓F) Remove ammeter from P1 pin 2. Install shunts in P1 pins 2, 3, 18 and 19. Install ammeter in series with P1 pin 4 and set for 1 amp full scale.
- ✓G) Turn on IDPU B and Instrument A power:  
/IDPUBPWR ON  
/INSTRAPWR ON
- ✓H) Measure and record the current measured: 61 mA
- ✓I) Record IDPU and instrument current from TCW display:  
IDPU 124 mA Instrument 59 mA

- ✓ J) Turn off IDPU B and Instrument A power:  
       /IDPUBPWR OFF  
       ✓ verify  
       ✓ /INSTRAPWR OFF  
       verify




- ✓ K) Remove ammeter and install all remaining shunts in connector.

7) Make the following measurements on S/C side of connector P4:

- ✓ A) Turn on MUE Port B: *Turn on IDPU: /S900KTLM /IDPUAPWR ON*

- ✓ B) Stimulate HCI and Sun Sensor with MUE GSE.

- ✓ C) Use oscilloscope to verify logic outputs as listed below:

2 T/MREQ } ALWAYS LOW, SIGNAL NOT RUNNING w/o Port A communication UP  
 3 T/MCLK } 100 nsec 1/5 Hz  
 4 PIPPER   
 9 EARTH/SPACE }  
 10 SPACE/EARTH } 1 msec at 1/5 Hz   
 11 1HZ ~ 50 nsec pulse at 1 Hz  
 12 2\*\*22 HZ (about 4.2 MHz) 

- ✓ D) Use oscilloscope to verify less than .1 volts on input T/MDATA on pin 14. OK - picking up clock

- ✓ E) Return to 4k telemetry: /s4ktlm

8) Make the following measurements on the S/C side of connector P8:

- ✓ A) Turn on MUE Port A:  
       /IDPUAPWR ON

- ✓ B) Use oscilloscope to verify logic outputs listed below:

2 Data A, MUE to IDPU } see a 2 msec packets occurring every 50-100 msec  
 10 Data B, MUE to IDPU }

- ✓ C) Send commands to set IDPU level commands low:

/IDPURESET OPERATE  
 /IDPUROMSEL BANK0  
 /IDPUARTSEL LOW

- ✓ D) Use oscilloscope to verify the following. Record the value as read from the scope screen in the space provided:

7	Reset, MUE to IDPU cpu	(low)	<u>low</u>
14	IDPUROM Select, MUE to IDPU cpu	(low)	<u>low</u>
15	IDPUART Select, MUE to IDPU cpu	(low)	<u>low</u>

- ✓ E) Send command to set IDPU reset high:

/IDPURESET RESET

- ✓ F) Use oscilloscope to verify the following. Record the value as read from the scope screen in the space provided:

7	Reset, MUE to IDPU cpu	(high)	<u>high</u>
14	IDPUROM Select, MUE to IDPU cpu	(low)	<u>low</u>
15	IDPUART Select, MUE to IDPU cpu	(low)	<u>low</u>

- ✓ G) Send commands to set the IDPU reset low and PROM select to bank 1:  
       /IDPURESET OPERATE  
       /IDPUROMSEL BANK1
- ✓ H) Use oscilloscope to verify the following. Record the value as read from the scope screen in the space provided:
- |    |                                 |        |             |
|----|---------------------------------|--------|-------------|
| 7  | Reset, MUE to IDPU cpu          | (low)  | <u>low</u>  |
| 14 | IDPUROM Select, MUE to IDPU cpu | (high) | <u>high</u> |
| 15 | IDPUART Select, MUE to IDPU cpu | (low)  | <u>low</u>  |
- ✓ I) Send commands to set the IDPU ROM to bank 0 and the UART select to high:  
       /IDPUROMSEL BANK0  
       /IDPUARTSEL HIGH
- ✓ J) Use oscilloscope to verify the following. Record the value as read from the scope screen in the space provided:
- |    |                                 |        |             |
|----|---------------------------------|--------|-------------|
| 7  | Reset, MUE to IDPU cpu          | (low)  | <u>low</u>  |
| 14 | IDPUROM Select, MUE to IDPU cpu | (low)  | <u>low</u>  |
| 15 | IDPUART Select, MUE to IDPU cpu | (high) | <u>high</u> |
- ✓ K) Send the command to set the IDPU UART select low:  
       /IDPUARTSEL LOW
- ✓ L) Use the oscilloscope to verify less than .1 volts on the logic inputs listed below:
- |    |                     |             |
|----|---------------------|-------------|
| 5  | Data A, IDPU to MUE | <i>open</i> |
| 12 | Data B, IDPU to MUE | <i>open</i> |
- 9) Make the following measurements on the IDPU side of connector P8:
- ~~A) Turn on IDPU and Instrument power:~~  
       ~~/IDPUAPWR ON~~                      *Already on*  
       ~~/INSTRAPWR ON~~
- OK ✓ B) Use the oscilloscope to verify the logic signals listed below:
- |    |                     |  |
|----|---------------------|--|
| 5  | Data A, IDPU to MUE | <i>Always low looks like low impedance</i> |
| 12 | Data B, IDPU to MUE | <i>Always low (i.e. not open)</i>          |
- OK ✓ C) Use the oscilloscope to verify less than .1 volts on the input lines listed below:
- |      |                               |                           |
|------|-------------------------------|---------------------------|
| ✓ 2  | Data A, MUE to IDPU           | } <i>look like inputs</i> |
| ✓ 7  | Reset, MUE to IDPU Processor  |                           |
| ✓ 10 | Data B, MUE to IDPU           |                           |
| ✓ 14 | IDPUROM Sel, MUE to IDPU Proc |                           |
| ✓ 15 | IDPUART Sel, MUE to IDPU Proc |                           |
- 10) Power down spacecraft.
- 11) Remove break-out boxes from connectors P1, P4, and P8 and mate connectors, installing UCB Dwg. A0131 Port B Passive Tap Assembly in series with connector P4. Mate A0131 to UCB GSE System using 50-foot DA15 extension cable. Install breakout boxes in harness side only. Record all connector mates and de-mates in log.
- 12) Power up spacecraft.

- ✓ 13) Run SHOMON2 on UCB SOC. Turn on IPDU power:  
/IDPUAPWR ON  
/IDPUBPWR ON  
/INSTRAPWR ON  
/INSTRBPWR ON

Record total current monitor on SOC: \_\_\_\_\_ (240 +/- 50 mA)  
SHOVAL PNEBCURR \_\_\_\_\_ (240 +/- 50 mA)

completed  
28 Jan 94

- ✓ 14) Perform check of IDPU functions by running STOL procedure  
IDPUCHECK. (Leaves IDPU powered off when complete.)

1-29-94

- 15) Connect breakout boxes to harness side only of connectors  
P15, P16A, and P16B.

- ✓ 16) Turn on all instrument power services:  
/IDPUAPWR ON  
/INSTRAPWR ON  
/IWBOOMPWR ON

- 17) Turn on all instrument controlled +28 volt power services:  
/IPWRLEVEL 3  
/ICDI VALUE=H'xxxxxx' (ESA HV enable code 1) B23CA6  
/ICDI VALUE=H'yyyyyy' (ESA HV enable code 2) BSF965  
/ICDI VALUE=H'F8FFFF' (All services on)  
/ICDI VALUE=H'F9FFFF' (All services on)

- 18) Record current readings below:

TCW Monitors:

IDPUCURR 263 mA  
INSTRCURR 372 mA  
IWBOOMCURR 0

UCB SOC Monitors:

MCMON1 282 mA  
MCMON2 314 mA  
MCMON3 8 mA

- X 19) Print page of SHOMON2 on UCB SOC. UCB PRINTER NOT YET INSTALLED  
BUT DATA IS RECORDED 28 JAN 94 - H0H

Use s/c  
CHASSIS FOR  
SCOPE GND  
- H0H

- ✓ 20) Use oscilloscope to verify voltage on all pins of connectors  
P5, P6, P7, P9, P10, P11, P12, P13, P14, P19, P22, P23, and  
P26 is less than .1 volts. OK OK OK OK OK OK OK OK OK OK OK

- ✓ 21) Use oscilloscope to verify voltage on all pins of 15, P16A,  
and P16B. Verify all values are less than .1 volts, except  
those listed below. For those listed, record value.

P15-11	+32	(+21 to +32 volts)
P15-13	+32	(+21 to +32 volts)
P16A-11	+32	(+21 to +32 volts)
P16A-12	+32	(+21 to +32 volts)
P16B-11	+32	(+21 to +32 volts)
P16B-12	+32	(+21 to +32 volts)

See  
Attached  
Data  
Sheet

- ✓ 22) Turn off all IDPU, Instrument, and Motor power:

/IWBOOMPWR OFF  
/INSTRAPWR OFF  
/INSTRBPWR OFF  
/IDPUAPWR OFF  
/IDPUBPWR OFF

Turn off partial power do  
do current mon calib.

cur = H'F9FFFF'

NOTE 1 - All these pins were clearly open as evidenced by 60 Hz pick up on scope while they were  
being checked - H0H 28 JAN 94

- 23) Demate breakout boxes from connectors P15, P16A, and P16B. Connect breakout boxes to connectors P16C, and P16D.

- 24) Use oscilloscope to verify voltage on all pins of P16C, P16D, P17A, P17B, P17C, P17D, and P21. Verify all values are less than .1 volts, except those listed below. For those listed, record value.



P16C-11	_____	(+21 to +32 volts)
P16C-12	_____	(+21 to +32 volts)
P16D-11	_____	(+21 to +32 volts)
P16D-12	_____	(+21 to +32 volts)
P17A-1	_____	(+21 to +32 volts)
P17A-2	_____	(+21 to +32 volts)
P17B-1	_____	(+21 to +32 volts)
P17B-2	_____	(+21 to +32 volts)
P17C-1	_____	(+21 to +32 volts)
P17C-2	_____	(+21 to +32 volts)
P17D-1	_____	(+21 to +32 volts)
P17D-2	_____	(+21 to +32 volts)
P21-1	_____	(+21 to +32 volts)

See  
attached  
Data  
Sheet



DOWN OUT OF  
ORDER AFTER  
step 20

- 25) Mate connectors P5, P6, P7, P9, P10, P11, P12, P13, and P14, and record in log.




P15-1



- 1 0
- 2 +5V
- 3 Nov. high logic level with clock 
- 4 OPEN with Nov. clock cross TACK
- 5 "
- 6 0
- 7 0
- 8 0
- 9 0
- 10 0
- 11 +32V
- 12 OPEN - low junk
- 13 +32V
- 14 Logic high with data out?  112V
- 15 +5V
- 16 ~0
- 17 OPEN 0
- 18 " 0
- 19 0
- 20 OPEN 0
- 21 0
- 22 OPEN
- 23 OPEN 0
- 24 "
- 25 "

P16 A-1

1	0
2	+5V
3	ARM clock 
4	0
5	OPEN 0
6	" "
7	" "
8	" "
9	0
10	OPEN "
11	+32V
12	+32V
13	OPEN 0
14	Data out 
15	1 MHz clock
16	OPEN 0
17	" "
18	0
19	OPEN 0
20	"
21	"
22	"
23	"
24	"
25	4

P16B-1

- 1 0
- 2 stroke
- 3 
- 4 open low
- 5 " "
- 6 " "
- 7 " "
- 8 " "
- 9 " "
- 10 " "
- 11 +32V
- 12 +32V
- 13 open w/low junk
- 14 Data 
- 15 1MHz clock 
- 16 0
- 17 0
- 18 0
- 19 open
- 20 open
- 21 "
- 22 "
- 23 "
- 24 0
- 25 open



w/low junk

clock



P16 C-1	0
2	strobe
3	clock
4	open
5	"
6	"
7	"
8	"
9	"
10	"
11	+32v
12	+32v
13	open
14	Data
15	1MHz
16	open
17	0
18	0
19	OPEN
20	"
21	0
22	OPAW
23	0
24	OPAW
25	"

ABD-1  
1 open  
2 stwhe  
3 clock  
4 open  
5 "  
6 "  
7 "  
8 0  
9 0  
10 open  
11 +32v  
12 +32v  
13 open  
14 Data  
15 LMH7  
16 open  
17 "  
18 "  
19 "  
20 "  
21 0  
22 open  
23 "  
24 "  
25 "

17A -

A1

A2

0

1

+32

2

+32

3

0

4

Stone

5

1094  
high

6

C

7

орбис

8

22

9

C

10

OPEN

(1)

C

12

logic here

(3)

опер

(K)

C

15

open

- P17B - A1 0  
 A2 0  
 1 +32  
 2 +32  
 3 0  
 4 store  
 5 logic high  
 6 open  
 7 "  
 8 "  
 9 0  
 10 0  
 11 open  
 12 logic high  
 13 open  
 14 "  
 15 0

P17 C - A1

A4	0
1	open
2	+32
3	+33
4	0
5	stone
6	logic high
7	0
8	open
9	"
10	0
11	0
12	logic high
13	0
14	open
15	"

17D-

A1 0

A2 0

1 +32v

2 +32v

3 open?

4 stroke

5 logic high

6 0

7 open

8 "

9 0

10 0


11 0

12 logic high

13 0

14 open

15 open



P21- A1 0  
 A2 OPEN  
 1 +32  
 2 OPEN  
 3 0  
 4 stable  
 5 logic high  
 6 0  
 7 0  
 8 OPEN  
 9 0  
 10 OPEN  
 11 0  
 12 logic high  
 13 0  
 14 0  
 15 0

PROCEDURE PART 2 -- Checkout of instrument interface connectors

RESISTANCE MEASUREMENTS MADE WITH S/C NOT POWERED:

Make the following measurements with a break-out box installed in the harness side of the connectors only.

1) P15 checkout:

- A) With the black probe of the ohmmeter connected to S/C ground, verify greater than 10 megohm to S/C ground on pins 4, 6, 7, 8, 9, 12, 18, 20, 21, 22, and 24.
- B) Verify less than 1 ohm to S/C ground on pins 1, 10, 16, 23, and 25.
- C) With the black ohmmeter probe connected to S/C ground, measure and record the resistance between the following pins and ground:

5	<u>OL</u>	(> 1K )
19	<u>101 K</u>	(> 1K )

2) P16A checkout:

- A) Verify greater than 10 megohm to S/C ground on pins 4, 6, 7, 13, 18, 20, 22, and 25.
- B) Verify less than 1 ohm to S/C ground on pins 1, 10, 16, 23, and 24.
- C) With the black ohmmeter probe connected to S/C ground, measure and record the resistance between the following pins and ground:

5	<u>OL</u>	(> 1K )
19	<u>~100K</u>	(> 1K )
8	<u>100 K</u>	(> 1K )
21	<u>100K</u>	(> 1K )
9	<u>100K</u>	(> 1K )

3) P16B checkout:

- A) Verify greater than 10 megohm to S/C ground on pins 4, 6, 7, 13, 18, 20, 22, and 25.
- B) Verify less than 1 ohm to S/C ground on pins 1, 10, 16, 23, and 24.
- C) With the black ohmmeter probe connected to S/C ground, measure and record the resistance between the following pins and ground:

5	<u>OL</u>	(> 1K )
19	<u>~100K</u>	(> 1K )
8	<u>100K</u>	(> 1K )
21	<u>100K</u>	(> 1K )
9	<u>100</u>	(> 1K )

3) P16C checkout:

- A) Verify greater than 10 megohm to S/C ground on pins 4, 6, 7, 13, 18, 20, 22, and 25.
- B) Verify less than 1 ohm to S/C ground on pins 1, 10, 16, 23, and 24.
- C) With the black ohmmeter probe connected to S/C ground, measure and record the resistance between the following



pins and ground:

5	<u>OL</u>	(> 1K )
19	<u>~ 100K</u>	(> 1K )
8	<u>100K</u>	(> 1K )
21	<u>100K</u>	(> 1K )
9	<u>100K</u>	(> 1K )

4) P16D checkout:

- A) Verify greater than 10 megohm to S/C ground on pins 4, 6, 7, 13, 18, 20, 22, and 25.
- B) Verify less than 1 ohm to S/C ground on pins 1, 10, 16, 23, and 24.
- C) With the black ohmmeter probe connected to S/C ground, measure and record the resistance between the following pins and ground:

5	<u>OL</u>	(> 1K )
19	<u>~ 104K</u>	(> 1K )
8	<u>100K</u>	(> 1K )
21	<u>100K</u>	(> 1K )
9	<u>100K</u>	(> 1K )

5) P17A checkout:

- A) Verify greater than 10 megohm to S/C ground on pins 8 and 15.
- B) Verify less than 1 ohm to S/C ground on pins 3, 6, 9, 10, 11, and 13, 14 OPEN and A1 shield and A2 shield.
- C) With the black ohmmeter probe connected to S/C ground, measure and record the resistance between the following pins and ground:

5	<u>18 MΩ</u>	(> 1K )
7	<u>OL</u>	(> 1K )
12	<u>18 MΩ</u>	(> 1K )
A1	<u>100K</u>	(> 1K )
A2	<u>100K</u>	(> 1K )

6) P17 B checkout:

- A) Verify greater than 10 megohm to S/C ground on pins 8 and 15.
- B) Verify less than 1 ohm to S/C ground on pins 3, 6, 9, 10, 11, and 13, 14 OPEN and A1 shield and A2 shield.
- C) With the black ohmmeter probe connected to S/C ground, measure and record the resistance between the following pins and ground:

5	<u>OL</u>	(> 1K )
7	<u>OL</u>	(> 1K )
12	<u>18 MΩ</u>	(> 1K )
A1	<u>100K</u>	(> 1K )
A2	<u>100K</u>	(> 1K )

7) P17C checkout:

- A) Verify greater than 10 megohm to S/C ground on pins 8 and 15.

B) Verify less than 1 ohm to S/C ground on pins 3, 6, 9, 10, 11, and 13, 14, and A1 shield and A2 shield.

C) With the black ohmmeter probe connected to S/C ground, measure and record the resistance between the following pins and ground:

5	18M	(> 1K )
7	OL	(> 1K )
12	18M	(> 1K )
A1	100K	(> 1K )
A2	100K	(> 1K )

8) P17D checkout:

A) Verify greater than 10 megohm to S/C ground on pins 8 and 15.

B) Verify less than 1 ohm to S/C ground on pins 3, 6, 9, 10, 11, and 13, 14, and A1 shield and A2 shield.

C) With the black ohmmeter probe connected to S/C ground, measure and record the resistance between the following pins and ground:

5	~18M	(> 1K )
7	OL	(> 1K )
12	~18M	(> 1K )
A1	100K	(> 1K )
A2	100K	(> 1K )

9) P21 Checkout:

A) Verify greater than 10 megohm to S/C ground on pins 8 and 15.

B) Verify less than 1 ohm to S/C ground on pins 3, 6, 9, 10, 11, and 13, 14, and A1 shield and A2 shield.

C) With the black ohmmeter probe connected to S/C ground, measure and record the resistance between the following pins and ground:

5	~18M	(> 1K )
7	OL	(> 1K )
12	~18M	(> 1K )
A1	100K	(> 1K )
A2	100K	(> 1K )

P13

-1 OL

-3 OL

-4 OL

-5 ~54K

-9 54K

-10 OL

-15 ~5M

-16 ~100K

-21 OL

-22 OL

-23 ~3.2

-24 ~3.2

-25 ~3.2

-26 ~3.2

-27 ~3.2

-28 ~3.2

-29 ~3.2

10) P22 Checkout:

A) Verify less than 1 ohm to S/C ground on pins 3, 4, 12, 15, 21, 22, 24, 25, and 26.

B) Verify greater than 10 megohm to S/C ground on pins 5, 13, 14, and 23.

10) P23 checkout.

A) Verify less than 1 ohm to S/C ground on pins 14, 16, 18, 19, 25, and 26.

B) Verify greater than 10 megohm to S/C ground on pins 2, 6, 7, 8, 11, 12, 13, 20, and 24.

P22

1 OL

2 ~2.2

3 ~54K

4 ~54K

5 ~54K

6 ~54K

7 ~54K

8 ~54K

9 ~54K

10 ~54K

11 OL

12 ~54K

13 ~54K

14 ~54K

15 OL

16 ~54K

17 ~54K

18 ~54K

# MEASUREMENTS MADE WITH SPACECRAFT POWERED

All voltage measurements are made with an oscilloscope and are referenced to S/C ground.

- ✓ 12) Power up spacecraft.
- ✓ 13) Run SHOMON2 on UCB SOC. Turn on IPDU, Instrument, and Motor power services:
  - /IDPUAPWR ON
  - /IDPUBPWR ON
  - /INSTRAPWR ON
  - /INSTRBPWR ON
  - /IWBOOMPWR ON
  - /IPWRLEVEL 3

Verify total current drawn by IDPU is 240 +/- 50 mA.  
Record current readings below:

TCW Monitors:

IDPUCURR	<u>164 mA</u>
INSTRCURR	<u>59 mA</u>
IWBOOMCURR	<u>0</u>

UCB SOC Monitors:

MCMON1	<u>141</u>
MCMON2	<u>0</u>
MCMON3	<u>0</u>

- ✓ 14) P15 checkout:
  - ✓ A) Turn on TEAMS only:
    - /ICDI VALUE=H'F90000'
    - /ICDI VALUE=H'F80203' (Services 1,2,5 on)
  - ✓ B) Use the oscilloscope to measure and record the voltage to S/C ground on the pins below:
 

11	<u>+32</u>	(Approx +28 Volts)
13	<u>+32</u>	(Approx +28 Volts)

- ✓ 15) P16A checkout:
  - ✓ A) Turn on ESA 1 HV only:
    - send HV enable commands
    - /ICDI VALUE=H'B23C46'
    - /ICDI VALUE=H'B3F905'
    - /ICDI VALUE=H'F80403' (Services 1,2,15 on)
  - ✓ B) Use the oscilloscope to measure and record the voltage to S/C ground on the pins below:
 

11	<u>+4V</u>	(Approx 0 Volts)
12	<u>+28V</u>	(Approx +28 Volts)

- ✓ C) Turn on ESA 1 LV only:
  - /ICDI VALUE=H'F80007' (Services 1,2,19 on)
- ✓ D) Use the oscilloscope to measure and record the voltage to S/C ground on the pins below:
 

11	<u>+28V</u>	(Approx +28 Volts)
12	<u>+4V</u>	(Approx 0 Volts)

- ✓ 16) P16B checkout:
  - ✓ A) Turn on ESA 2 HV only:
    - /ICDI VALUE=H'F80803' (Services 1,2,16 on)
  - ✓ B) Use the oscilloscope to measure and record the voltage to S/C ground on the pins below:
 

11	<u>+4V</u>	(Approx 0 Volts)
12	<u>+28V</u>	(Approx +28 Volts)

- ✓C) Turn on ESA 2 LV only:  
/ICDI VALUE=H'F8000B' (Services 1,2,20 on)
- ✓D) Use the oscilloscope to measure and record the voltage to S/C ground on the pins below:
- |    |             |                    |            |
|----|-------------|--------------------|------------|
| 11 | <u>+28v</u> | (Approx +28 Volts) | 27.955 sec |
| 12 | <u>+4v</u>  | (Approx 0 Volts)   |            |
- ✓17) P16C checkout:
- ✓A) Turn on ESA 3 HV only:  
/ICDI VALUE=H'F81003' (Services 1,2,17 on)
- ✓B) Use the oscilloscope to measure and record the voltage to S/C ground on the pins below:
- |    |             |                    |
|----|-------------|--------------------|
| 11 | <u>+4v</u>  | (Approx 0 Volts)   |
| 12 | <u>+28v</u> | (Approx +28 Volts) |
- ✓C) Turn on ESA 3 LV only:  
/ICDI VALUE=H'F80013' (Services 1,2,21 on)
- ✓D) Use the oscilloscope to measure and record the voltage to S/C ground on the pins below:
- |    |             |                    |         |
|----|-------------|--------------------|---------|
| 11 | <u>+28v</u> | (Approx +28 Volts) | 27.955v |
| 12 | <u>+4v</u>  | (Approx 0 Volts)   |         |
- ✓18) P16D checkout:
- ✓A) Turn on ESA 4 HV only:  
/ICDI VALUE=H'F82003' (Services 1,2,18 on)
- ✓B) Use the oscilloscope to measure and record the voltage to S/C ground on the pins below:
- |    |             |                    |
|----|-------------|--------------------|
| 11 | <u>+4v</u>  | (Approx 0 Volts)   |
| 12 | <u>+28v</u> | (Approx +28 Volts) |
- ✓C) Turn on ESA 4 LV only:  
/ICDI VALUE=H'F80023' (Services 1,2,22 on)
- ✓D) Use the oscilloscope to measure and record the voltage to S/C ground on the pins below:
- |    |             |                    |        |
|----|-------------|--------------------|--------|
| 11 | <u>+28v</u> | (Approx +28 Volts) | 27.955 |
| 12 | <u>+4v</u>  | (Approx 0 Volts)   |        |
- ✓19) P17A and P17B checkout: (Tests done on both connectors.)
- ✓A) Turn on Rad 1 & 2 Motor Power only:  
/ICDI VALUE=H'F80003' (Services 1,2 on)  
/ICDI VALUE=H'F90100' (Service 25 on)
- ✓B) Use the oscilloscope to measure and record the voltage to S/C ground on the pins below:
- |        |             |        |             |                           |
|--------|-------------|--------|-------------|---------------------------|
| P17A-1 | <u>+4v</u>  | P17B-1 | <u>+4v</u>  | (Approx 0 Volts)          |
| P17A-2 | <u>+32v</u> | P17B-2 | <u>+32v</u> | (Approx +28 Volts) 31.197 |
- ✓C) Turn on Radial 1 & 2 LV only:  
/ICDI VALUE=H'F80043' (Services 1,2,6 on)  
/ICDI VALUE=H'F90000'
- ✓D) Use the oscilloscope to measure and record the voltage to S/C ground on the pins below:
- |        |             |        |             |                    |        |
|--------|-------------|--------|-------------|--------------------|--------|
| P17A-1 | <u>+28v</u> | P17B-1 | <u>+28v</u> | (Approx +28 Volts) | 27.834 |
| P17A-2 | <u>+4v</u>  | P17B-2 | <u>+4v</u>  | (Approx 0 Volts)   |        |

- ✓ 20) P17C and P17D checkout: (Tests done on both connectors.)
- ✓ A) Turn on Rad 3 & 4 Motor Power only:  
       /ICDI VALUE=H'F80003' (Services 1,2 on)  
       /ICDI VALUE=H'F90100' (Service <sup>26</sup>25 on)
- ✓ B) Use the oscilloscope to measure and record the voltage to S/C ground on the pins below:
- |        |             |        |             |                           |
|--------|-------------|--------|-------------|---------------------------|
| P17C-1 | <u>+4v</u>  | P17D-1 | <u>+4v</u>  | (Approx 0 Volts)          |
| P17C-2 | <u>+32v</u> | P17D-2 | <u>+52v</u> | (Approx +28 Volts) 31.197 |
- ✓ C) Turn on Radial <sup>3</sup>1 & <sup>4</sup>2 LV only: <sup>8</sup>8  
       /ICDI VALUE=H'F80043' (Services 1,2, <sup>23</sup>6 on)  
       /ICDI VALUE=H'F90000'
- ✓ D) Use the oscilloscope to measure and record the voltage to S/C ground on the pins below:
- |        |             |        |             |                           |
|--------|-------------|--------|-------------|---------------------------|
| P17C-1 | <u>+28v</u> | P17D-1 | <u>+28v</u> | (Approx +28 Volts) 27.884 |
| P17C-2 | <u>+4v</u>  | P17D-2 | <u>+4v</u>  | (Approx 0 Volts)          |
- ✓ 21) P21 checkout:
- ✓ A) Turn on Axial Boom LV Power only:  
       /ICDI VALUE=H'F80103' (Services 1,2,24 on) 27.884
- ✓ B) Use the oscilloscope to measure and record the voltage to S/C ground on the pin below:  
       P21-1 +28 (Approx +28 Volts)
- ✓ 22) P19 and P26 checkout.
- ✓ A) Connect UCB Dwg. No. A0125 Mag Boom Test Panel to P19 and P26. Need 6-foot DE9 extension cable to make connection.
- ✓ B) Run SHOMAGSW on UCB SOC. ✓ \ IDEPPAIR ~~IDEPPAIR~~ MAG
- ✓ C) Press TURNMAG\_A button on Mag Boom Test Panel.
- ✓ D) Hold for two seconds, then release.
- ✓ E) In DEPLOY STAT window see LENG7 value increment by two.
- ✓ F) Press TURNMAG\_B button on Mag Boom Test Panel.
- ✓ G) Hold for two seconds, then release.
- ✓ H) In DEPLOY STAT window see LENG8 value increment by two.
- ✓ I) In MON 140 window see MAGLATA value greater than 3.7v 2.000V.
- ✓ J) Press and hold MAGLAT\_A button on Mag Boom Test Panel.
- ✓ K) In MON 140 window see MAGLATA value less than 0.300V 0.0v within one minute.
- ✓ L) Release MAGLAT\_A button.
- ✓ M) In MON 140 window see MAGLATB value greater than 4.2 v 2.000V.
- ✓ N) Press and hold MAGLAT\_B button on Mag Boom Test Panel.
- ✓ O) In MON 140 window see MAGLATB value less than 0.300V 0.00 within one minute.
- ✓ P) Release MAGLAT\_B button.

✓ 23) P22 checkout.

✓ A) Install ETU Flux gate Magnetometer into connector P22 using 26S-26S gender changer.

✓ B) Set up to test Flux Gate Mag by sending commands:

/IDPURESET RESET /5900K TLM  
/IDPURESET OPERATE  
/IPWRLEVEL VALUE=3  
/ISVCXMIT VC2=1, VC2X=1, VC3=1, VC4=1, VC5=1  
/ISETBIT ADR=H'F9', BIT=0 (Service 7 on)  
/ISETBIT ADR=H'F9', BIT=1 (Service 8 on)  
/ICDI VALUE=H'A80000'  
/ICDI VALUE=H'800000'  
/ICDI VALUE=H'827100'  
/ICDI VALUE=H'D90000'  
/ICLRBIT ADR=H'D8', BIT=8 (Enable Survey 0)  
/ICLRBIT ADR=H'D8', BIT=9 (Enable Survey 1)  
/ICLRBIT ADR=H'D8', BIT=10 (Enable Survey 2)  
/ISETBIT ADR=H'F8', BIT=14 (Service 4 on)  
/ISETBIT ADR=H'F8', BIT=15 (Service 3 on)

✓ C) Run SHOFLUX on UCB SOC.

✓ D) Rotate ETU Magnetometer in Earth's field. Verify appropriate change in display.

✓ 24) P23 checkout.

✓ A) Measure and record voltages as listed below:

9	<u>+5</u>	(Should be +5 Volts)
15	<u>+11v</u>	(Should be +15 Volts)
17	<u>-10v</u>	(Should be -15 Volts)

✓ 25) Turn off all IDPU, Instrument, and Motor power:

/IWBOOMPWR OFF  
/INSTRAPWR OFF  
/INSTRBPWR OFF  
/IDPUAPWR OFF  
/IDPUBPWR OFF

✓ 26) Power down spacecraft.

Remove ETU Flux Gate Magnetometer.