



PFR-119 Title: BAU IDPU current draw readback incorrect

Assembly : ETU BAU	SubAssembly : PCM	
Component : ITOS Conversions	Units Affected:	Units fixed:
Originator: Ellen Taylor	- - - - -	- - - - -
Organization: Swales/UCB	Date: 11/30/05	
Phone: (510) 643-4054	Email : ertaylor@ssl.berkeley.edu	

Failure Occurred During (Check one ✓)

✓ Functional test ☐ Qualification test ☐ S/C Integration ☐ Launch operations ☐ Other (Flight Assy)

Environment when failure occurred:

✓ Ambient ☐ Vibration ☐ Shock ☐ Acoustic
☐ Thermal ☐ Vacuum ☐ Thermal-Vacuum ☐ EMI/EMC

Problem Description

During the P2 Probe post-ship Aliveness Test on 11/30/05, the IDPU current monitor read incorrectly on the Swales delivered EGSE ITOS machine (xenon). The UCB ITOS machines had the correct conversion, indicating a difference in the ITOS databases.

Analyses Performed to Determine Cause
--

The Aliveness Test was done with the EDU BAU. The flight BAU has the correct conversion.

Corrective Action/ Resolution

This PFR was closed per THM-MINT-PROC-101 F2 PFR Close-out Procedure on 3/2/06. The IDPU and Instruments were turned on one at a time (providing 5 points from ~220mA to 500mA). The current readback from the BAU and the IDPU BAU reported telemetry was compared against expected values.

Acceptance:

MAM: Ron Jackson _____; MSE: Ellen Taylor _____

PM: Peter Harvey _____; Cognizant Engineer _____

Date of Closure _____